



检 验 报 告

℃ ℃

Foshan Supervision Testing Center of Quality and Metrology

National Center of Inspection and Testing for Ceramic Sanitary and Plumbing Fixture



| | | | |
|--|---|--|--------------------------|
| | FTG °C °C 1200mm×2700mm×9mm M ----- | | -----/----- ----- |
| | | | 3 / |
| | | | 2025 03 21 |
| | | | 2025 03 22 2025 04 17 |
| | GB/T 39156-2020 () | | JC/T 908-2013 () |
| | GB/T 39156-2020 () | | |
| | 14 21 | | GB/T 39156-2020 |
| | | | 冲 |
| | ----- | | |

吴博

程进峰

程海静



| | | | | | |
|----|-------|----------|------|-------|-------|
| 1 | mm | | 2.0 | -0.4 | -0.2 |
| | | | 2.0 | -0.5 | -0.2 |
| | | | 0.5 | -0.1 | +0.1 |
| | | | 2.0 | 0.3 | |
| | | | 2.0 | 0.4 | |
| | | | 0.5 | 0.4 | |
| 2 | % | 7.5mm °C | 0.15 | -0.01 | +0.01 |
| | mm | | 3.5 | 0.4 | |
| | % | 7.5mm °C | 0.15 | -0.03 | +0.03 |
| | mm | | 2.0 | 0.4 | |
| 3 | ----- | | | | |
| 4 | % | | 0.5 | 0.04 | |
| | | | 0.6 | 0.03 | 0.05 |
| 5 | N | 7.5mm , | 1500 | 2691 | |
| 6 | MPa | | 35 | 54 | |
| | | | 32 | 53 | 56 |
| 7 | ----- | | | | |
| 8 | ----- | | | | |
| 9 | ----- | | | | |
| 10 | ----- | | 0.50 | 0.64 | 0.66 |
| 11 | ----- | | 3 | 5 | |
| 12 | ----- | | GB | GA | |
| 13 | ----- | | GLB | GLA | |

| | | | | | |
|----|-----------------------|--------------------------|--------------------------|---------------------------|------------------------|
| 14 | | ----- | | GHA | ----- |
| 15 | | ----- | | 6000 | 4 |
| 16 | | -1 | | 5.9 | 10⁻⁶ |
| 17 | | % | | 0.01 | ----- |
| 18 | | ----- | | 0.84 | ----- |
| 19 | 值 | mg/L | 值 | 0.5 | ----- |
| | | mg/dm² | | 0.02 | |
| 20 | 值 | mg/L | 值 | 0.05 | ----- |
| | | mg/dm² | | 0.002 | |
| 21 | | ----- | ----- | 7 | ----- |
| 22 | I_{Ra} | ----- | A | I_{Ra} 1.0 | A |
| | | ----- | B | I_{Ra} 1.3 | |
| | ----- | A | I_r 1.3 | | |
| | I_r | ----- | B | I_r 1.9 | 1.0 |
| | | C | I_r 2.8 | | |

C

G25-WT2945

